




PR	29689 N
P1	1187603 N
P2	82404 N
PK	Since there is no braking system on the counterweight, it has not been calculated.

E-E PITH DETAIL




C-C MACHINE LOCATION



A-A DETAIL

B-B DETAIL



D - D SHAFT DETAILS

katre Lift